
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO



Miscellaneous Reports on Wells

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the

work was witnessed by an agent of the Comm a notary public. See additional instructions i	ission. Reg n the Rule	ports on minor operations need not s and Regulations of the Commissio	be signed and sworn to before n.
		report by checking below:	
REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WEI	LL
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WEI	LL
REPORT ON RESULT OF PLUGGING OF WELL	x		
		Artesia, N. Mex.	Feb. 24, 1944
OIL CONSERVATION COMMISSION, Gentlemen: SANTA FE, NEW MEXICO. Following is a report on the work done and th OIL & Refining Co. Company or Operator		State Well	No. in the
NW → SW → of Sec.	26	, T. 1. S , R , R , R	26 E , N. M. P. M.,
Wildcat	Field,	DeBaca	County.
The dates of this work were as follows: Feb	. 20th w	ork completed, work start	ed Jan. 5, 1944
Notice of intention to do the work was (was n	ot) submitt	ed on Form C-102 on	n. 3, 19.44
and approval of the proposed plan was (was r	not). obtaine	ed. (Cross out incorrect words.)	
DETAILED ACCOU	NT OF WO	RK DONE AND RESULTS OBTAI	NED
The hole was filled with mud from at 1600' and 5 sacks of cement plant approximately 90' of 7" casing withen filled with mud up to the bithen pulled, approximately 120'. The hole was filled with mud to cement placed on the bridge. The regulation marker set.	laced on as left ottom of of 8½° c 500°, at a hole w	the bridge. The 7" casi in the hole from 1533' to the 84" casing at 980'. asing was left in the hol that point a bridge was as then filled to the sur	ng was then pulled, 1623° . The hole was The $8\frac{1}{4}^{\circ}$ casing was e from 860° to 980° . set and 5 sacks of face with mud and a
Witnessed by Rerold Kersey Name	Dane		
Subscribed and sworn before me this	th	is true and correct.	Kersey
day of February	, 19. 44	Position Agent	
I lovem MI Do	a la	RepresentingDancige:	Company or Operator
My commission expires 0ct. 18, 1945		l4th Floor, W	V. T. Waggoner Bldg.
Nota	ry Public	Address Fort Worth	eres

Remarks:

##