



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 100-10556
Lease No. _____
Unit **RECEIVED**

JUL 16 1962

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
OFFICE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 26, 1961

Well No. 117 is located 1930 ft. from N line and 15 ft. from E line of sec. 15
Sec. 15 (Range) 15 (Meridian) New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4120 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Total Depth 1300'
2. Spotted out plug 1200-1250'
3. Spotted out plug 600-550'
4. Left well open for rancher to test for water above 550'
5. No fresh water found; so,
5. Spotted 10 sack cement plug at 100 feet.
6. Spotted 2 sack cement plug at top of surface pipe.
7. Installed dry-hole marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company S. B. Phipps
Address Box 1174
Deming, New Mexico
By H. Dale Nichols
Title Geologist

[illegible]