

| | |
|---------------------------|------------|
| NUMBER OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| TRANSPORTER | OIL GAS |
| PRODUCTION OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

FORM C-103
(Rev 3-55)

(Submit to appropriate District Office by January 1, 1966)

| | | | | | | | |
|----------------------------------------------------|------------------------|-------------------------|----------------------|----------------------------------------------|----------------------|--|--|
| Name of Company Midwest Refining Company | | | | Address Box 476, Carrollton, Texas | | | |
| Lease State | Well No. #1 | Unit Letter A | Section 16 | Township 33-S | Range 14-W | | |
| Date Work Performed February 13, 1962 | Pool Wildcat | | | County Hidalgo | | | |

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Since the last report was filed, work has been done in removing from the hole large boulders which had hampered drilling operations and which had caused a crooked hole. Also, the hole itself has been straightened and made ready for further drilling. However, extreme weather conditions during most of the past month have made it impossible for workmen to reach the wellsite with trucks and tractors and move to the wellsite the larger rig which is now needed for continuation of drilling. It is contemplated, weather permitting, that necessary roads will be built and the larger rig moved into the wellsite. Operations have also been hampered by the fact that the undersigned, Mac T. Hall, President of Midwest Refining Company, has, for several weeks, been hospitalized in St. Paul's Hospital in Dallas, Texas, where he is still confined.

| | | |
|--------------|----------|---------|
| Witnessed by | Position | Company |
|--------------|----------|---------|

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

| | | | | |
|--------------------------|--------------|------------------------|--------------------|-----------------|
| D F Elev. 4535 | T D | P BTD | Producing Interval | Completion Date |
| Tubing Diameter | Tubing Depth | Oil String Diameter | Oil String Depth | |
| Perforated Interval(s) | | | | |
| Open Hole Interval | | Producing Formation(s) | | |

RESULTS OF WORKOVER

| Test | Date of Test | Oil Production BPD | Gas Production MCFPD | Water Production BPD | GOR Cubic feet/Bbl | Gas Well Potential MCFPD |
|-----------------|--------------|--------------------|----------------------|----------------------|--------------------|--------------------------|
| Before Workover | | | | | | |
| After Workover | | | | | | |

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

| | |
|-----------------------------------|--------------------------------------------|
| Approved by <i>Joe Kaptain</i> | Name <i>Mac T. Hall</i> |
| Title <i>District Engineer</i> | Position President |
| Date <i>February 29, 1962</i> | Company Midwest Refining Company |