

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 071276
Unit _____

APPROVED
APR 30 1963
A. R. BROWN
DISTRICT ENGINEER

RECEIVED

MAY 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

APR 15, 1963

Well No. 1 is located 713 ft. from N line and 686 ft. from E line of sec. 22

30 4 NW 4 30 (1/4 Sec. and Sec. No.) 30 4 (Twp.) 14 (Range) N. 41. 4. 4. (Meridian)
WILCOX (Field) WILCOX (County or Subdivision) NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged and abandoned as follows:
Well was found to be bridged at approximately 30 feet and was cemented from the bridge to the surface. A 4 foot piece of 4 inch pipe was left as a surface marker with the location chiseled on the pipe.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEW MEXICO

Address WILCOX, NEW MEXICO

By J. F. Sherry

Title J. F. Sherry