

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 064819
Unit J. F. Heard

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... April 24, 19 51

Well No. 1 is located 1980 ft. from N line and 1980 ft. from W line of sec. 33

SE/4 of NW/4 6-S 9-E -
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lincoln County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5892 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Abandonment procedure:

1. Ran Schlumberger electric log from 4504-8050' (TD).
2. Ran dipmeter survey.
3. Ran gamma ray and neutron survey from surface to 8050' (TD).
4. Spotted plug #1 on bottom from 7971-8050' w/30 sacks cement.
5. Spotted plug #2 from 4394-16' w/30 sacks cement. Could not feel plug. Respotted plug #2 from 4362-4440'. Found plug.
6. Recovered 1918' of 9 5/8" casing.
7. Spotted following remaining cement plugs: #3, 1910-2013' w/40 sacks cement.
#4, 1430-95' w/51 sacks cement.
#5, surface to 30' w/45 sacks cement

8. Recovered rods and 7" casing in water well
9. Moved rig off location. (10) Cleaned location, as well as possible at present.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Unable to completely fill mud and waste pits as pits were not sufficiently dry to

Company STANDARD OIL COMPANY OF TEXAS work.

Address Box 1660

Midland, Texas

By H. W. Mathews

Title Div. Prod. Supt.