

Land Office New MexicoLease No. 012962

Unit _____

MAY 1 1963

SC. C.

ARTESIA OFFICE

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 18, 1958

Well No. 1 is located 660 ft. from N line and 2180 ft. from W line of sec. 15

N W 15

(1/4 Sec. and Sec. No.)

4 S

(Twp.)

16 E

(Range)

N.M.P.M.

(Meridian)

Waldcat

(Field)

Lincon

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Filled hole with mud

Set 50' cement plug 1725 - 1775

knocked off 5 1/2" casing at 1,225' & pulled

Knocked off 6 3/8" casing at 1135' & pulled

Set 50' cement plug at 1525 - 1575

Set 50' cement plug at 1325 - 1375

Set 50' cement plug at 500' - 550'

Set regulation marker & cleaned location

TO 1962

RECEIVED

APR 26 1963

U. S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Albuquerque Exploration, Inc.Address 309 Carlisle Ave. N.E.Albuquerque, New MexicoBy C. O. ZulaTitle Agent