Budget Bureau No. 42-R358.4. (SUBMIT IN TRIPLICATE) UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY** SUNDRY NOTICES AND REPORTS ON WELLS NOTICE OF INTENTION TO DRILL. SUBSEQUENT REPORT OF WATER SHUT-OFF NOTICE OF INTENTION TO CHANGE PLANS..... SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING... NOTICE OF INTENTION TO TEST WATER SHUT-OFF. SUBSEQUENT REPORT OF ALTERING CASING. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... SUBSEQUENT REPORT OF ABANDONMENT.... NOTICE OF INTENTION TO PULL OR ALTER CASING..... SUPPLEMENTARY WELL HISTORY NOTICE OF INTENTION TO ABANDON WELL.... (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) April 26 is located 660 ft. from line and 1900 ft. from (14 Sec. and Sec. No.) (Range) **Vildeat** (Field) (County or Subdivision) APR 27 1962 The elevation of the derrick floor above sea level is ft. U. S. GEOLOGICAL SURVEY DETAILS OF WORK ROSMELL SE (State names of and expected depths to objective sands; show sizes, weights, and lengths of proping points, and all other important proposed work) On April 23, 1962, 35 sax of cament were spotted with the bottom of the drill pipe positioned at 950' from the surface which places a 90' cement plus inmediately below the Clorieta Sand, another 20 sack plug was spotted at \$50° back up to the stup of the 9 5/8 casing which was shot off at 395'. A 5 sack cement plug was placed in the top of the 13 3/8 surface cosing, along with the required marker. The final surface clean up on this location will be delayed until the ris is moved from the location and at that time the U.S.C.S. vill be advised so that the final inspection can be made. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

ELLIOTT PRODUCTION COMPANY

Forwell, New Mexico

Fox 1355

Company

Address

By Vice President