

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.  
Form Approved.

Land Office

Lease No.

Unit

NM 02421

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 10, 1964

Well No. 1 <sup>Miller</sup> is located 590 ft. from N line and 2010 ft. from E line of sec. 30  
18S 6E 18S 18E  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
18S 6E 18S 18E  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cemented from 780' to 700' filled to 620' with mud, shot 10' pipe off. Pulled same cemented 90', filled to 15'. Put cement and marker to surface. Cleaned location.

RECEIVED

JUN 26 1964

O. C. C.  
ARTESIA, OFFICE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Miller Drilling Co.

Address 2303, Bandoline

Donnell, N. Mex.

By [Signature]

Title Owner, (partner)