

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company J. D. Cone				Address 318 North Alleghaney, Odessa, Texas		
Lease #1 Ralph Peirson	Well No. 1	Unit Letter K	Section 12	Township T-9-S	Range R14E	
Date Work Performed 9/14/60	Pool Wildcat			County Lincoln County, New Mexico		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

45 sacks regular El Toro cement plugged to T.D. 1006 ft. via Haliburton Oil Well Cementing Company. Mud used through 5 1/2 inch casing from 658' - 1006ft. Then 7 inch casing o' thru 658 ft. 6' 4 1/2" marker erected in place. Slush pit leveled by bulldozer per agreement with mining supervisor of nearby thorium establishment.

Witnessed by Haliburton Employees	Position	Company
---	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

M L Armstrong

Name

D. D. D. D.

Title

Position

Owner

Date

JAN 8 '61

Company

OIL CONSERVATION COMMISSION	
ARTESIA DISTRICT OFFICE	
No. Copies Received	4
DISTRIBUTION	
OPERATOR	2
LAND AREA	1
PRODUCTION OFFICE	
STATE LAND OFFICE	
INVESTIGATOR	
DATE	1 - 1 - 19
REMARKS	