HO. 401 COPIES RE	CEIVED			l						Form C			
DISTRIBUT	ЮИ										des Old nd C-103	!	
ANTA FE		11_		NE	EW MEXICO O	IL CONS	ERVATION	COMMISSION	i de an gar	Effectiv	e 1-1-65		
ILE		<u> </u>	v'_	İ					r	5a. Indicate	Toma	1.000	·····
.s.G.S.		<u> </u>		ĺ				2 12 see	7.54	State X			•• 🗀
ND OFFICE		Ц						1000 大豆蒜	101	5. State Oil	<u> </u>		
PERATOR		Щ_	<u> </u>	ĺ								_euse 140.	•
								<u></u>		LG - 80	7777	m	m
,		SŲ	NDR	Y NOTICES	AND REPOR	RTSON	WELLS	PERENT RESERVOI	<u>j</u> M.				
(50 40. 03	USE	ABP	LICAT	ION FOR PERMIT	FORM C-10	1) FOR SUC	H PROPOSALS	.)		7. Unit Agr	eement 1	iame	77777
01L	GAS	רעת	1	•						,, O			
WELL			}	OTHER-				<del></del>		8. Form or	l ense N	ame	
Name of Operato		r-TIN	N E1:	M CO /					İ	DUNLAP			
		<u>EIK(</u>	)L.EU	M CO. /						9. Well No.		·	
Address of Oper		ALLOI	IN D	HITE DINC /M	ד חואה דו	EYAS 70	2701			]			
		AUIJI	114 6	UILDING/M	IULAND, I	L AH3 /:	7701			10. Field a	nd Pool.	or Wilde	at
Location of Well	T		1	980	T FROM THE	SOUTH		660		WILDCAT			
UNIT LETTER _	<u> </u>	<u> </u>		JOU FEE.	T FROM THE		LINE AND		FEET FROM	m	m	77777	77777
	EAST			25		2S		19 E			11111		
THE	<u></u> ,	LINE, S	SECTIO		TOWNSHIP		RANG	Ε	RMPM.		11111		
mm	m	777	rr	i um	Elevation (Shor	w whether	DF. RT. GR	esc.)		12. County		1111	<i>HHH</i>
		////		////////////	4847	.9' GR				12. County LINCOLI	1		
<u> </u>	777777	77.7	777.	77777								(11111	<i></i>
•	,	Che	ck.	Appropriate	Box To Inc	licate N	ature of	Notice, Repo					
	NOTI	CEC	FIN	TENTION T	го:			SUBS	SEQUENT	REPORT	OF:		
		_							<del></del>				
ERFORM REMEDIAL	. WORK	ال		_	PLUG AND ABA	HDON	REMEDIAL	WORK	닖		ALTERIN	G CASING	님
EMPORARILY ABAH	DON	]		•				DRILLING OPHS.	<u> X</u>		PLUG AND	ASANDON	MENT
ULL OR ALTER CAS	11NG	ل			CHANGE PLANS	لـا	CASING TE	ST AND CEMENT JO	* [X]				
- •	4,						OTHER	. <u> </u>	·				
STHER	<del></del>					—— LJ							
Describe Propo	osed or Co	omp.et	ed Or	ergtions (Clear	rly state all per	tinent det	ails, and giv	ve pertinent dates	e, including	estimated do	te of su	arting any	proposed
work) SEE RU	LE 1103.	•	·		•								
•											•		
	Shudda	d w	11م	with 17 1	/2" hole	on 3-1	0-81 and	d drilled t	to 842'.	Ran 2	l its		4
	12 3/8	(U W	12#	H-40 cas	ing set @	845'.	Cemen	ted with 35	50 sx HL	W + 4%	CaČl,		
	15 5/6	Th	ive.	+ + 4% Ca	.cl. 350 s	x HLW	+ 4% Ca(	Cl, and tai	iled in	with 20	0 sx		
	120 37	2%		irculated	300 sx to	pit.	Waiting	g on rotary	/ table	repairs	•		•
		L // •	Ŭ	,, сата се	000 011 00	F		<b>,</b>	•	•		•	
							<b></b>	0 1540	ADTUCDO	<b>-</b> 71 -			
								C, LAND, PA	AKINEKS,	, F1LE			
. 1 hereby certify	y that the	infor	nation	above is true	and complete to	the best	of my knowl	edge and belief.					
	_				-				•				
$\mathcal{Q}$	P./1	lin	th	5	-	TTLE R	EGULATO	RY COORDINA	ATOR	DATE_	MARC	н 13,	1981
	_	1		, , ,	1								
	1/2/		[1]	Man		ITLE	OH, AMD (	GAS INSPECTO	'	_ DATE _	MAR	1 7 19	181
PROVED BY	111/11	<u> </u>	111	1110-00									