

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Drawn by
Artesia
88210

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A	RECEIVED BY FEB -9 1987 O. C. D. ARTESIA, OFFICE	5. LEASE DESIGNATION AND SERIAL NO. NM 37128
2. NAME OF OPERATOR Yates Petroleum Corporation ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with State requirements. See also space 17 below.) At surface 1980 FNL & 1980 FEL, Sec. 27-T2S-R19E		8. FARM OR LEASE NAME Chisum "AAW" Federal
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4954' GR	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT Wildcat- Aco
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit G, Sec. 27-2S-19E
		12. COUNTY OR PARISH Lincoln
		13. STATE NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

TD 4100'. Well was plugged and abandoned as follows:

- Plug #1: 2750-2650' w/35 sx Class "C" 2% CaCl2. PD 11:15 PM 1-17-85.
WOC 2 hrs. Tagged plug at 2640'.
Plug #2: 2360-2260' w/35 sx Class "C" 2% CaCl2. PD 2:00 AM 1-18-85.
WOC 1 hr. Tagged plug at 2250'.
Plug #3: 1250-1150' w/35 sx Class "C" 2% CaCl2. PD 3:45 AM 1-18-85.
WOC 1 hr. Tagged plug at 1140'.
Plug #4: 50'-surface w/10 sx Class "C" 2% CaCl2. PD 5:30 AM 1-18-85.

Post ID-2
2-1-85
P&A

Gene Lee notified Chuck Flaherty with BLM in Roswell, 1-17-85, before plugging well.
Dry hole marker installed. Surface will be cleaned and restored.

18. I hereby certify that the foregoing is true and correct

SIGNED Granita Doulet TITLE Production Supervisor DATE 1-18-85
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
DATE
PETER W. CHESTER
JAN 30 1987

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA