

(SUBMIT IN TRIPLICATE)

Office ScLease No. 051688-C

Unit _____

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 9, 1954

Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 15NW¹ of NW¹ Sec. 15 20-S 9E N.M.P.M.
(Or Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat (Field) Otero (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was spudded on August 7, 1954.

Set 20" casing at 155' w/250 sacks of cement, cement circulated.
20" conductor pipe was tested to 500 psi for thirty minutes.
Pressure at start of test 500 psi. Pressure at end of the test 500 psi.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Plymouth Oil CompanyAddress Box 1860Midland, TexasBy Neal A. Taylor
(Neal A. Taylor)
Title Dist. Petr. Engr.

