



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **063271**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 4, 1962

Well No. **01** is located **330** ft. from **N** line and **1650** ft. from **W** line of sec. **22**

NE 1/4 of NW 1/4 (1/4 Sec. and Sec. No.) **213** (Twp.) **16E** (Range) _____ (Meridian)
VC (Field) **Otero** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above **Ground** level is **5376** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 2255- Test Fresh Water at TD. Well was abandoned to Rancher, Runyan Brothers, Inc. Quit Claim is being issued and all of pipe was turned over to Runyan Brothers, Inc.

RECEIVED

FEB 21 1963

RECEIVED
DEC 5 1962
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Lefers Petroleum Corporation**

Address **Pampa, Texas**

Pecos Drilling Company, Inc.

By **G. Husler**

Title **Agent**