

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office **Santa Fe**
Lease No. **MM 053410**
Unit **VED****APPROVED**
AUG 23 1961
A. R. BROWN
ACTING DISTRICT ENGINEER**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 9,**1961**

Well No. **10001** is located **200** ft. from **XXN** line and **400** ft. from **E** line of sec. **7**
SE SE **Sec. 7** **230** **16E** **W4PA**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox **Stark** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was plugged and abandoned as follows:

- (1) Pelled 2-1/8" casing at 1257'.
- (2) Set cement plug from 2400-2500', 250-250', and in top and bottom of surface pipe.
- (3) Located location and set surface marker

Location ready for inspection.**RECEIVED****AUG 22 1960**
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **G. P. Campbell**Address **2127 San Mateo NE****Albuquerque, New Mexico**

By

Ben Doregan**Geologist**

Title