

# Memo

From  
Bill Gressett  
Oil & Gas Inspector

To

was drilled as O.K. Hearte

#1 Evans

TD 3763

Comp. May 21, 1931

Temp. abnd. 7-6-37

P. A. 4-20-39

on 2-1-59 an attempt was made  
to clean out & test. found junk  
@ 340. Could not clean it out  
P + A

Form 9-381a  
(Feb. 1951)Budget Bureau No. 42-R358.4.  
Approval expires 12-31-60.

New Mexico


Land Office

011866

Lease No.

Unit

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of intention to reenter and test old hole <input checked="" type="checkbox"/>	

test old hole

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 18, 1958, 19

Well No. 1 Evans is located <sup>2270</sup>~~2320~~ ft. from S line and 330 ft. from E line of sec. 22  
NW SW 22 2h South, 12 East NMP  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wilcat Otero New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5014 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to reenter the Fred Turner No. 1 Evans hole and clean out to 2000 feet and test. If oil production is encountered we propose to cement 5 1/2 inch casing through the prospective pay. If no shows are encountered we propose to return the hole and location to its present condition.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. P. CampbellAddress 711h Central StAlbuquerque, New Mexico

By

Ben Donegan

Title

Ben Donegan  
Geologist