

BURRO CANYON UNIT #1

Date	T.D.	2030' FSL & 2100' FEL of Section 2, T-21S, R-20-E. Otero County, New Mexico.
12/15/78	89'	Drilling 89' (6' in 8 hrs.) lime (DSS 17).
12/16/78	95'	Drilling 95' (6' in 8 hrs.) Lime (DSS 18).
12/17/78	101'	Drilling 101' (6' in 8 hrs.) Lime (DSS 19).
12/18/78	107'	Drilling 107' (6' in 8 hrs.) Lime (DSS 20).
12/19/78	113'	Drilling 113' (6' in 8 hrs.) Lime (DSS 21).
12/20/78	115'	Drilling 115' (2' in 8 hrs.) Lime. (DSS 22).
12/21/78	115'	(Shut down due to snow) Lime.
12/22/78	117'	Drilling 117' (2' in 8 hrs.) Lime. (DSS 23).
12/23/78	119'	Drilling 119' (2' in 8 hrs.) Lime. (DSS 24).
12/24/78	121'	Drilling 121' (2' in 8 hrs.) Lime. (DSS 25).
12/25/78	123'	Drilling 123' (2' in 8 hrs.) Lime. (DSS 26).
12/26/78	125'	Drilling 125' (2' in 8 hrs.) Lime. (DSS 27).
12/27/78	127'	Drilling 127' (2' in 8 hrs.) Lime. (DSS 28).
12/28/78	129'	Drilling 129' (2' in 8 hrs.) Lime. (DSS 29).
12/29/78	131'	Drilling 131' (2' in 8 hrs.) Lime. (DSS 30).
12/30/78	133'	Drilling 133' (2' in 8 hrs.) Lime. (DSS 31).
12/31/78	135'	Drilling 135' (2' in 8 hrs.) Lime. (DSS 32).
1/1/78	138'	Drilling 128' (3' in 8 hrs.) Lime. (DSS 33).
1/2/78	141'	Drilling 141' (3' in 8 hrs.) Lime. (DSS 34).
1/3/78	145'	Drilling 145' (4' in 8 hrs.) Lime. (DSS 35).
1/4/78	148'	Drilling 148' (3' in 8 hrs.) Lime. (DSS 36).
1/5/78	151'	Drilling 151' (3' in 8 hrs.) Lime. (DSS 37).
1/6/78	155'	Drilling 155' (4' in 8 hrs.) Lime. (DSS 38).
1/7/78	160'	Drilling 160' (5' in 8 hrs.) Lime. (DSS 39).
1/8/78	164'	Drilling 164' (4' in 8 hrs.) Lime. (DSS 40).
1/9/78	165'	Drilling 165' (1' in 3 hrs.) Lime. Preparing to cement 13 7/8" csg. (DSS 41).