

BURRO CANYON UNIT #1

Date	T.D.	2030' FSL & 2100' FEL of Section 2, T-21S, R-20-E, Otero County, New Mexico.
3/27/78	413'	TD 413', Lime. Fishing.
3/28/78	413'	TD 413', Lime. Fishing.
3/29/78		No Report
3/30/78	413'	TD 413', Fishing
3/31/78	413'	TD 413', Fishing, Running 2-7/8" tbg, Bowen Jars. 7-5/8" O.D. overshot and 10-1/2" Guide.
4/1/78	413'	TD 413', Fishing. (DSS 89).
4/2/78	413'	TD 413', Recovered Fish. (DSS 90).
4/3/78	413'	TD 413', Lime. Cleaned hle out to TD.
4/4/78	413'	TD 413', Shut Down to repair rig.
4/5/78	420'	Drlg. 420' (7' in 8 hrs.) Lime. (DSS 93).
4/6/78	433'	Drlg. 433' (13' in 8 hrs.) Lime. (DSS 94).
4/7/78	444'	Drlg. 444' (11' in 8 hrs.) Lime. (DSS 95).
4/8/78	456'	Drlg. 456' (12' in 8 hrs.) Lime. (DSS 96).
4/9/78	469'	Drlg. 469' (13' in 8 hrs.) Lime. (DSS 97).
4/10/78	486'	Drlg. 486' (17' in 8 hrs.) Lime. (DSS 98).
4/11/78	506'	Drlg. 506' (20' in 8 hrs.) Lime. (DSS 99).
4/12/78	525'	Drlg. 525' (19' in 8 hrs.) Lime. (DSS 100).
4/13/78	541'	Drlg. 541' (16' in 8 hrs.) Lime. (DSS 101).
4/14/78	549'	Drlg. 549' (8' in 8 hrs.) Lime. Encountered 2' cavern at 543' (DSS 102).
4/15/78	560'	Drlg. 560' (21' in 8 hrs.) Lime. (DSS 103).
4/16/78	578'	Drlg. 578' (18' in 8 hrs.) Lime. (DSS 104).
4/17/78	590'	Drlg. 590' (12' in 8 hrs.) Lime. (DSS 105).
4/18/78	605'	Drlg. 605' (15' in 8 hrs.) Lime. (DSS 106).
4/19/78	622'	Drlg. 622' (17' in 8 hrs.) Lime. (DSS 107).
4/20/78	639'	Drlg. 639' (17' in 8 hrs.) Lime. (DSS 108).
4/21/78	657'	Drlg. 657' (18' in 8 hrs.) Lime. (DSS 109).