

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

AUG 22 1978

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. LG-1845	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

B. G. C.
ARTERIA, OFFICE

1. OIL WELL ☐ GAS WELL ☒ OTHER- Wildcat		7. Unit Agreement Name
2. Name of Operator Terra Resources, Inc.		8. Farm or Lease Name Burro Canyon Unit
3. Address of Operator 200 Wall Towers West, Midland, TX 79701		9. Well No. 1-Y
4. Location of Well UNIT LETTER J, 2030 FEET FROM THE South LINE AND 2080 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 21-S RANGE 20E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 5145' GR		12. County Otero

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☒	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-22-78 Ran 36 joints of 8 5/8", K-55, 24 #/ft casing to 1553'. Cemented with 200 sx RFC, 850 sx Class C neat, 200 sx RFC. Cement did not circulate to surface. Bumped plug with 650 #, Float held, ran temperature survey and found top at 710'. Followed with 17 plugs w/1" pipe (1) 75 sx RFC (2) 75 sx RFC (3) 75 sx RFC (4) 75 sx RFC (5) 35 sx RFC (6) 35 sx RFC & 4 yards gravel (7) 35 sx RFC (8) 35 sx RFC (9) 35 sx RFC (10) 35 sx RFC (11) 35 sx RFC, cement @ 338' (12) 16 yards ready mix, cement @ 148' (13) 30 sx RFC (14) 35 sx RFC (15) 35 sx RFC (16) 35 sx RFC, cement @ 60' (17) 50 sx RFC, 3 yards ready mix, TOC-surface, WOC time - 12 hrs, pressure tested to 650 # for 30 minutes, held OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Homero G. Gracia TITLE Area Operations Engineer DATE 8-21-78

APPROVED BY W. G. Susselt TITLE SUPERVISOR, DISTRICT II DATE AUG 25 1978
CONDITIONS OF APPROVAL, IF ANY:

WIRE LINE SERVICE

305 McARTHUR
ARTESIA, NEW MEXICO 88210
Phone 745-3281

TEMPERATURE SURVEY

RECEIVED

OPERATOR W. J. GAYNES

WELL Artesia Canyon

WELL NO. Unit- 1

WELL

DATE & TIME OF SURVEY 7/22/78

DATE & TIME SURVEY MADE 7/22/78 12:00 A.M.

SURVEY RUN BY Billy Joe Cathey

DATUM

WELL DATA St. 710 ft.

O. C. C.
ARTESIA, OFFICE

"SECOND"
COPY

TEMPERATURE IN °F

