

J-2-215-20E

Terra Resources Inc. Burro Canyon^{1st}

Markers OK - Plastic left in pits -

Oil filters laying in pasture south of loc.

1 5 gal. bucket + 1 tire next to road
about 1/4 mile from loc.

11-22-78

NEW MEXICO OIL CONSERVATION COMMISSION - ARTESIA, NEW MEXICO