

(SUBMIT IN TRIPLICATE)

Land Office N.M.Lease No. 02259UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED

MAR 2 1961

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 20, 19 61

Well No. 1 is located 1780 ft. from S line and 660 ft. from E line of sec. 33  
NE / SE 14-South 29-East (Meridian)  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
W. C. Chaves New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3829 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Re-enter Honolulu Oil & Gas Corporation No. 1 North Mullis Unit well;  
Set bridge plug at or about 1400 Feet, perforate and test Yates-Seven Rivers  
formation.

Location Plat and required logs are presently in your files.

RECEIVED

FEB 23 1961

U. S. GEOLOGICAL SURVEY  
ALBUQUERQUE, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Hilary D. Mahin & A. L. HowardAddress 326 Central BuildingMidland, Texas

By

A. L. Howard

Title

Co-Operator