

Copy to

Las Cruces

Land Office

062351

Lease No.

Lucky Lakes Area

Unit

1 Sec. #405

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Yates-Kimes

Artesia, New Mexico.

November 1, 1948

Well No. 1 is located 660 ft. from [N] line and 659 ft. from [E] line of sec. 28
NE 1/4 Sec. 28 15 S., 29 E. N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Chaves New Mexico.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per conversation with Frank Stahl, filled hole with aquajel from 1755 to total depth of 3762'. Spotted 10 foot cement plug from 3600 to 3610 feet. Spotted 17 sack cement plug in bottom of pipe from 1755 to 1808'. Filled hole to top with water and put 3" gate valve on top of pipe. This work was done October 26, 1948.

RECEIVED
NOV 9 1948

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Martin Yates, Jr.

Address Box 397,
Artesia, N. Mex.

By [Signature]
 Title Unit Operator.