

Read & Stevens, Inc. #1 Blackmar State Com.
990' FSL & 990' FWL Sec. 7, T-15-S, R-28-E
Chaves County, New Mexico

DST #1 (Atoka sand) 8326'-8484', open total of 90 min. On 30 min. pre-flow, open w/fair blow increasing to good blow. On 60 min. final flow, open w/weak blow, continuing throughout. No gas to surface. Rec. 310' drlg. mud, no show. IHP 4030#, 30 min. IFP 227#-315#, 75 min. ISIP 524#, 60 min. FFP 402#-437#, 90 min. FSIP 524#, FHP 4083#, BHT 137°.

DST #2 (Atoka sand) 8325'-8587', open total of 90 min. On 30 min. pre-flow, open w/very weak blow, increasing. No GTS. On 60 min. final flow, open w/strong blow, has GTS in 12 min. of final flow, FTP built to 9 PSI on 1/4" ch. @ rate of 35,000 CFGPD, then declined to 1/2 PSI, gas TSTM. Rec. 310' drlg. mud. IHP 4030#, 30 min. IFP 385#-385#, 60 min. ISIP 1886#, 60 min. FFP 280#-245#, 120 min. FSIP 1957#, FHP 3995#, BHT 137°.

SP DST #3 (Cisco lime) 7360'-7450', misrun.

SP DST #4 (Cisco lime) 7349'-7439', open total of 65 min. On 30 min. pre-flow, open w/very weak blow, increasing to weak blow in 5 min. and decreasing to very weak blow at end of pre-blow. On 35 min. final flow, open w/very weak blow and died in 5 min. No GTS. Rec. 50' drlg. mud, no show. IHP 3630#, 30 min. IFP 85#-107#, 60 min. ISIP 1771#, 35 min. FFP 85#-150#, did not take FSIP. FHP 3546#.

SP DST #5 (Yeso ?) 2770'-2860', misrun.