

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)USE
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0557563

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1.	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	JUL 16 1975
2.	NAME OF OPERATOR Dalport Oil Corp.	O. C. C. ARTESIA, OFFICE
3.	ADDRESS OF OPERATOR 3471 First National Bank Bldg., Dallas, TX	
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FN & 660' FWL	
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7.	UNIT AGREEMENT NAME
8.	FARM OR LEASE NAME Todhunter-Federal
9.	WELL NO. 2
10.	FIELD AND POOL, OR WILDCAT Lucky Lake South-Queen
11.	SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22, 15S-29E
12.	COUNTY OR PARISH Chaves
13.	STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) oil string

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 1875 7-4-75

Ran 6 joints new 4 $\frac{1}{2}$ -9 $\frac{1}{2}$ "#, 39 joints new 4 $\frac{1}{2}$ -10.5"#, total 1862' at 1872'.
Floatshoe at bottom, insert float at top of bottom joint. 3 centralizers,
10 scratchers. Cemented w/ 125 sx lite, 150 sx 'c', 50% Poz, 2% gel, 8#
salt/sack. Plug down 2:00 PM.

RECEIVED
JUL 15 1975
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED John M. HarpTITLE geologistDATE 7-9-75

(This space for Federal or State office use)

APPROVED BY John A. Kraft
CONDITIONS OF APPROVAL, IF ANY:TITLE DISTRICT ENGINEERDATE JUL 15 1975

*See Instructions on Reverse Side