

NMOCC COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

RECEIVED

| | | | |
|---|--|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 5. LEASE DESIGNATION AND SERIAL NO. NM-7301 | |
| 2. NAME OF OPERATOR Harvey E. Yates Company | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| 3. ADDRESS OF OPERATOR P. O. Box 1933, Roswell, N. M. 88201 | | 7. UNIT AGREEMENT NAME | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL | | 8. FARM OR LEASE NAME East Lake Arthur Federal | |
| 14. PERMIT NO. | | 9. WELL NO. 2 | |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3442.6' GL | | 10. FIELD AND POOL, OR WILDCAT Wildcat | |
| | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-15S, R-27E | |
| | | 12. COUNTY OR PARISH Chaves | |
| | | 13. STATE N. M. | |

MAY - 3 1978

O. C. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | MULTIPLE COMPLETE <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | ABANDON* <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| (Other) <input type="checkbox"/> | |

SUBSEQUENT REPORT OF:

| | |
|---|--|
| WATER SHUT-OFF <input type="checkbox"/> | REPAIRING WELL <input type="checkbox"/> |
| FRACTURE TREATMENT <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/> |
| (Other) Spud, run casing, etc <input checked="" type="checkbox"/> | |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-7-78 Spudded 12 1/4" hole.

Ran 6 joints (242') 8 5/8" OD 20# R-3 casing set at 249' and cemented with 120 Sx C1 C with 2% CaCl. Plug down 2:15 pm. Circulated 15 Sx.

WOC 23 Hours.

Test Casing to 500#. OK.

RECEIVED

MAY 1 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul J. Harder

TITLE Engineer

DATE 4-28-78

(This space for Federal or State office use)

APPROVED BY

Lee S. Lara

TITLE ACTING DISTRICT ENGINEER

DATE MAY 2 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side