

**APPROVED**OCT 21 1953  
RONNIE E. SHOOK  
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 061023Unit RECEIVED

OCT 22 1953

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL	<i>Temporarily Abandoned</i>	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 0 is located 000 ft. from S line and 000 ft. from E line of sec. 13, 1903  
 (Section and Sec. No.) 13 (T. 17S R. 27E S. 18PM (Meridian)  
 (Field) Edley (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

" 1150' set plug 8" hole w/10 in bridge. Pulled 8 5/8" csg. set plug @ surface wtr. @ 300' w/10 in. Pulled 10" csg. Full description welded on marker. Shut inf for possible water flood.

*Well is temporarily abandoned.*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sims & Roese Oil CompanyAddress 200 Becker BuildingArtesia, New MexicoBy R. L. HeinsohlTitle Partner