

APPROVE
AUG 23 1962
Ronnie E. Shook
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces
Lease No. LC 064023
Unit _____

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

751
OK
Unit I

RECEIVED
AUG 27 1962
O. C. C.
MEXIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT & Plugging	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 10, 1954

Saunders
Well No. 8 is located 1650 ft. from N line and 990 ft. from E line of sec. 13
 SW/NE/SE 17S 27E N7PM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
 Empire Eddy New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was cemented with five sacks of cement which covered the Seven Rivers formation and some additional ten feet of hole. The remainder of the hole was filled with mud and a regulation four inch marker was set and cemented.

All seven inch pipe was retrieved from the hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Simms & Reese Oil Company
 Address Bujac Bldg.
Carlsbad, N.M.
 By /s/ R. L. Heinsch
 Title Partner