



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC 003579**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico 1-3-1957

Well No. **1** is located **340** ft. from **N** line and **1980** ft. from **E** line of sec. **26**

340 (1/4 Sec. and Sec. No.) **10 S** (Twp.) **25 E** (Range) **114W** (Meridian)

Artesia (Field) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **3411** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

per our oral conversation of 1-3-57 we have plugged and abandoned this well as follows:

Set a plug of 10 sacks of cement in bottom. (To 2000').
Filled with mud to 300 ft & set bridge & 25' cement plug.
Filled with mud to surface & cemented collar with 20 sacks.
Put up regulation marker & cleaned up location.
A 5/8" casing landed at 422 feet was all recovered.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Almquist & Watson**

Address **Box 836, Artesia, N. M.**

By *G. R. Holmer*

Title **Agent**