

RECEIVED  
JUL 1 1951  
SUBMIT IN TRIPLICATE  
OIL COUNTY  
Artesia

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **LAS CRUCES**  
Lease No. **015818 (a)**  
Unit **1**

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 30, 1951

Well No. **10** is located **2300** ft. from **S** line and **130** ft. from **W** line of sec. **16**  
**10** (1/4 Sec. and Sec. No.) **17S** (Twp.) **28E** (Range) **1241W** (Meridian)  
**Empire** (Field) **Sady** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 500' of 7" O.D. casing, cemented with 15 sacks cement on June 18, 1951.  
 On June 22, 1951 drilled plug, hole tested dry. Knocked off pipe at 328'  
 and ran 10 sacks of cement at stub, leaving 172' of 7" O.D. pipe in hole.  
 Pulled 328' of 7" O.D. pipe. Filled the hole with mud, circulated to the  
 top and set cement marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **A. E. ROVER (OIL TOP LEASE)**  
 Address **ARTESIA, NEW MEXICO**  
 c/o Kenneth Tyner  
 Star Route East  
 Artesia, New Mexico  
 By *[Signature]*  
 Title **Agent**

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 015010 (a)  
Unit 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 20 is located 2300 ft. from N line and 330 ft. from E line of sec. 18  
18 (1/4 Sec. and Sec. No.) 18 (Twp.) 18 (Range) 18 (Meridian)  
El Paso (Field) El Paso (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 500' of 7" O.D. casing, cemented with 15 sacks cement on June 18, 1951.  
On June 22, 1951 drilled plug, hole tested dry. Knocked off pipe at 328'  
and ran 10 sacks of cement at stub, leaving 172' of 7" O.D. pipe in hole.  
Pulled 328' of 7" O.D. pipe. Filled the hole with mud, circulated to the  
top and set cement barrier.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company A. H. BLUER (OLD TOP LEASE)

Address ARTESIA, NEW MEXICO

c/o Kenneth Tyson  
Star Route East  
Artesia, New Mexico

By [Signature]  
Title Agent