UNITED STATES

Unit REMOVED

Land Office LAS LIVES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

DEG 2 1959

SUNDRY NOTICES AND REPORTS ON WELLS TERIA, IDEFFICE

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MAR	K NATURE OF REPORT, NOTICE, OR OTHER DATA)
·	
	less Hills, Ess Marien Houseper 24 , 19 59
Well No. 25 is located 660 ft. from	$\begin{bmatrix} N \\ S \end{bmatrix}$ line and $\begin{bmatrix} S \\ S \end{bmatrix}$ line of sec. $\begin{bmatrix} L \\ S \end{bmatrix}$
(½ Sec. and Sec. No.) (Twp.)	(Range) (Meridian)
Phah Lonesone Edd	yor Subdivision) (State or Territory)
(Field) (County	for Subdivision) (State of Territory)
The elevation of the derrick floor above sea le	evel is 3747 ft.
DETA	AILS OF WORK
	sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- l other important proposed work) 7
we drilled plug, bailed hale down a drilling was resumed.	d up on excist to 3100 pale. After 72 hours, and re-rem tailer. As invi-off proved complete
After fracturing well, we pulled 10 from 440' to 300'.	3/1" casing loose and apotted 50 sacks cement
Command and pressure testing done	by Lenton Mil Well Commanting Company.
I understand that this plan of work must receive approval	in writing by the Geological Survey before operations may be commenced.
Company General Merican Cil Comp	sumy of Texas
Address P. C. Sox 416	
Loco Mills, New Mexico	By Rotions
	R. J. Beard
	Title District Superintendent