



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. 70060 543
Unit 4

RECEIVED

JAN 29 1963

SUNDRY NOTICES AND REPORTS ON WELLS C. C.
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
Deepen to Lovington Zone	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 21, 1963

Well No. 25 is located 1280 ft. from N line and 660 ft. from E line of sec. 25
NE/4 Sec. 25 16E 31E 100N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Deepen with Rotary tools from 3415 to 3565 and fracture treat Lovington Zone.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWMONT OIL COMPANY

Address ADLEY BUILDING

ARTESIA, NEW MEXICO

ORIGINAL SIGNED BY
H. J. LEDBETTER

By _____

Title Superintendent