

Form 9-381a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**

Lease No. **060970**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 18

1948

Well No. 1 is located 660 ft. from N line and 600 ft. from EW line of sec. 30
SW SW 16S # 31E NMPM
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We mudded hole from 3155' to 3000'. Set 10 sack cement plug from 3000' to 2950'. Knocked 5½' off at 1400' and pulled same. Set 15 sack cement plug from 1410' to 1360'. Mudded hole from 1360' to 510'. Set 10 sack cement plug from 510' to 480'. Tried to pull 8' and it wouldn't come. Mudded to surface and cemented marker. then cleaned location for inspection.

RECEIVED

NOV 19 1948

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Boyd-Plemmons drilling Company

Address 112 South Second, Artesia, New Mexico

By Thamox Boyd

Title Partner