

Form 9-331a
(March 1942)

Budget Bureau No. 42-358
Approval expires 11-30-42

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 060545
Unit Grlier

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 10 is located 660 ft. from SW line and 1980 ft. from W line of sec. 30
SW 1/4 Sec. 30 16 S. 31 E. N.M.P.M.
Square Lake Eddy New Mexico
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned well, using tubing method and filling the hole with mud. Then set plug with 10 sacks cement in base of 5 1/2" pipe. and plug with another 10 sacks cement at stub of 7" pipe above red sands. Another Knecked off 7" at 1950' and recovered 1929' of same. Another plug using 15 sacks cement was placed at top of salt, plugging completed with regulation marker cemented at surface and location cleaned.

U. S. G.

1949