

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office LCLease No. 00336Unit 6

RECEIVED

AUG 28 1963

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	XX
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 21, 1963

**Texas Trading** ✓  
Well No. 4 is located 1900 ft. from N line and 1500 ft. from E line of sec. 33  
SW 1/4 Sec. 33 16-2 3-5 NMPH  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Square Lake Lady New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-16-63 Acidize with 500 gallons of 15% regular acid thru perf. at  
3405-13, 3449-54, 3459-63, 3471-77, 3481-93, 3503-15.

RECEIVED  
AUG 28 1963  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HELMONT OIL COMPANYAddress Rowley BuildingArtesia, New MexicoORIGINAL SIGNED BY  
H. J. LEDBETTERBy [Signature]Title Superintendent