NO. OF COPIES RECEIVED	Form C-103	
DISTRIBUTION	Supersedes Old	
SANTA FE / NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103	
FILE /	Effective 1-1-65	
U.S.G.S.	5a. Indicute Type of Lease	
LAND OFFICE	State Fee X	
OPERATOR C	5. State Off & Gas Lease No.	
OPERATOR D. D. C.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DELPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
I. OIL GAS WELL OTHER-	7. Unit Agreement Name	
2. Name of Operator	Tom Brown "GO" Com 8. Fam or Lease Name	
	e. Fam of Lease Name	
Yates Petroleum Corporation V 3. Aduress of Operator		
	9. Well No.	
207 S. 4th Street, Artesia, New Mexico 88210		
	10. Field and Pool, or Wildcat	
UNIT LETTER R35 FEET FROM THE NORTH LINE AND FEET FROM	Kennedy Farms Morrow	
THE West LINE, SECTION 22 TOWNSHIP 17S 26E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.) 3339' GR; 3356' KB	12. County Eddy	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data	
NOTICE OF INTENTION TO:		
SOLSEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT	
OTHER Test and evaluate	e IXI	
OTHER		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1 103.	estimated date of starting any proposed	
The production packer @ 8299 was removed from the well. A retrievable placed @8430' a production packer was set @8300'. These tools separat perforation (8398'-8402') from all other perforations open in this well perforations was then tested as follows:	ed the upper Morrow 1. The upper Morrow	
2/9/79: SITP = 2200 psi, Opened well to the pit, the tubing pressu	IC TETT TO 400 bet TH	

one half hour. SI.
2/10/79: SITP = 1800 psi, (15 hours). Put well on production pressure fell to line pressure (500 psi) in 1.5 hours. SI
2/11/79: SITP = 1510 psi (23 hours). Put well on production pressure fell to line pressure (500 psi) in 1.5 hours.
2/12/79: TP = 500 psi. Gas volume too small to measure. SI.
2/13/79: SITP = 1110 psi (24 hours)
2/14/79: SI
2/15/79: SITP = 1563 psi. Ran bottom hole pressure test (1959 psi @ 8300')
2/20/79: SITP = 1656 psi. Flared well to pit on 12/64" choke. Opened well @3:30 PM (TP 1656 psi) at 4:30 PM FTP was 510 psi at 8:30 PM FTP was 5 psi, gas volume was too small to measure. Flowed well an additional 12 hours. Gas volume too small to measure. SI.
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE

DATE ____

TITLE ____

TITLE_

SEE PAGE 2.

SIGNED

APPROVED BY ____

NO. OF COPIES RECEIVED	7			
DISTRIBUTION	-	Form C-103 Supersedes Old		
SANTA FE		C-102 and C-103		
FILE		SERVATION COMMISSION	Effective 1-1-65	
U.S.G.S.	-			
	-1		Sa. Indicate Type of Lease	
OPERATOR	4			
	_J		5. State Cil & Gas Lease No.	
SUNDA DO NOT USE THIS FORM FOR FOR USE "MAPPLICAT	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPEN OR PLUG B	WELLS		
[].	The contract of the contract of the sol	H PROPOSALS.)	7. Unit Agreement Name	
OIL GAS WELL	0THER-			
2. Name of Operator		······································	Tom Brown "GO" Com 8. Farm of Lease Name	
Yates Petroleum Corpo	ration		a. Ferm of Lease Name	
3. Address of Operator				
	tesia, New Mexico 88210		9. Well No.	
4. Location of Well	cesia, New Mexico 88210		1 1	
	005	1000	10. Field and Pool, or Wildcat	
UNIT LETTER	835 FEET FROM THE North	LINE AND FEET FROM	Kennedy Farms Morrow	
West		265		
THE LINE, SECTI	22 175	ZOG	AIIIIIIIIIIIIIIIIIIIIIII	
	15. Elevation (Show whether		12. County	
$\overline{\mathbf{U}}$	3339' GR: 3	3356' KB	Eddy	
16. Check	Appropriate Box To Indicate N	lature of Notice. Report or Orl	er Data	
NOTICE OF I	NTENTION TO:		REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	A STAR ABOUNDENT	
	·	OTHER Test and evaluation	ate X	
OTHER	· _ []]		L. ²	

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Tom Brown Continued - Page 2

2/22/79: SITP 580 psi (24 hours); SITP 640 psi (32 hours) 2/23/79: SITP 740 psi (48 hours) 2/24/79: Removed bridge plug @ 8430' and production packer @8300' from the well. 2/25/79: Went into the well with on and off tool and sliding sleeve (closed) latched into production packer @8442'. Swabbed well to flow. After cleaning up, well flowed @370 psi on 1/2" choke (1.7 MMCF/D). SI. SITP (4 hours) 2125 2/26/79: SITP 2140 psi (16 hours)

THE LOWER MORROW PERFORATIONS (8504-8512) ARE NOW BEING TESTED FOR PRESSURE AND PERFORMANCE. THIS IS AN INTERIM REPORT.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	nr	m	2	\underline{r}	
APPROVI	hi.	a, "	Si	esse	T

TITLE Production Superintendent

2/27/79 DATE

SUPERVISOR, DISTRICT II

FEB 2 7 1979

CONDITIONS OF APPROVAL, IF ANY: