

2. *Explain the importance of the following:*

[illegible]

|       |       |    |       |    |
|-------|-------|----|-------|----|
| Yucca | 3566' | GL | 1000' | GL |
|-------|-------|----|-------|----|

3-17-80 F.R. 1-14-80  
(Seven Rivers)  
TD 1000'; Complete  
Perf (Seven Rivers) 810-818'  
Frac (810-818') 42,000 gals + 45,000# sd  
LOG RUN: GRNL  
3-22-80 COMPLETION ISSUED

IC 30-015-70011-80