

Form 9-331  
Dec. 1973Form Approved  
Budget Bureau No. 42-R1424UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well2. NAME OF OPERATOR  
Yates Petroleum Corporation3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 882104. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330' FNL & 1650' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE

NM 28007

6. IF INDIAN, ALLOTTEE OR TRIBE NAME 4

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Sivley "PY" Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Unit C, Sec. 9-T16S-R30E

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit C, Sec. 9-T16S-R30E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3825.5' GR.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 12-1/4" hole at 6:30 AM 4-15-81. TD 525' - Ran 14 joints of 7" 23# ST&C K-casing set at 525'. 1-Texas Pattern guide shoe at 525'. Flapper float insert at 484'. Cemented w/200 sacks 65-35 Poz and 3% CaCl. Tailed in w/150 sacks Class "C" 3% CaCl. Compressive strength of cement - 1280 psi in 12 hours. PD 7:45 PM 4-16-81. Bumped plug to 500 psi, released pressure and float held okay. Cement circulated 25 sacks to pit. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 6-1/4". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

*Peter W. Chester*

TITLE

Engineering  
Secretary

DATE

4-28-81

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:ACCEPTED FOR RECORD  
PETER W. CHESTER

TITLE

DATE

APR 30 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

See instructions on Reverse Side

RECEIVED  
APR 29 1981  
Set @