Form 3160-5 (June 1990)	UNITED ST DEPARTMENT OF		FORM APPROVED Budget Bureau No. 1004-0135				
	BUREAU OF LAND I		Expires: March 31, 1993 5. Lease Designation and Serial No. LC-064050				
	SUNDRY NOTICES AND F in for proposals to drill or to e "APPLICATION FOR PEF	deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name				
	SUBMIT IN TR	IPLICATE	7. If Unit or CA, Agreement Designation				
1. Type of Well Gas		224 1 10	8. Well Name and No.				
	Other		Trigg Federal #1				
2. Name of Operator SDX Resources, Inc.		A SEP 200 3	9. API Well No.				
3. Address and Telephone N		CCD ARTESIA	30-015-30956				
PO Box 5061, Midlar		UUD AITLON w/	10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage 530' FNL 1650' FEL	Sec., T., R., M., or Survey Description)	St	Red Lake (
Sec 26, T17S, R27E		281 21110168h	11. County or Parish, State				
		CD ARTESIA W	Eddy Co., NM				
12. CHECK A	PPROPRIATE BOX(s) TO IN	IDICATE NATURE OF NOTICE, REPORT, C	OR OTHER DATA				
TYPE OF \$	SUBMISSION	TYPE OF ACTION					
Notice of	Intent	Abandonment	Change of Plans				
		Recompletion					
Subseque	ent Report	Plugging Back	Non-Routine Fracturing				
		Casing Repair	Water Shut-Off				
Sincl Aba	and an area of Nietian	• •	Conversion to Injection				
Final Aba	indonment Notice	Altering Casing	Conversion to Injection				
13. Describe Proposed or C	ompleted Operations (Clearly state all per	• •	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is				
 Describe Proposed or C directionally drilled, give Request approval to McQuadrangle LWC formations. SDX proposes to lay McQuadrangle's SW attached). An archar 	ompleted Operations (Clearly state all per subsurface locations and measured and f dispose of produced water form f - Red Lake Grayburg Unit water a 3" SDR-11 poly line on top of t /D plant located in Unit L of Sec 3 elogical survey has been request le the additional produced water	Altering Casing Altering Casing Other Temporary ROW Interference Temporary ROW	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 				



5

Water Analysis Report by Baker Petrolite

SDX RESOURCES TRIGG FED WELL #1 WELLHEAD

Account Manager RANDY ALLISON

Summary	/	Analysis of Sample 130727 @ 75°F								
Sampling Date	6/12/00	Anions	mg/l	meq/l	Cations	mg/l	meq/l			
Analysis Date	6/20/00	Chloride	125594	3543	Sodium	76879	3344			
Analyst	JOANNA RAGAN	Bicarbonate	255	4.18	Magnesium	839	69.0			
		Carbonate	0.00	0.00	Calcium	3626	181			
TDS (mg/l or g/m²)	210843	Sulfate	3037	63,2	Strontium	59.0	1.35			
Density (g/cm³ or tonne/m³)	1.138	Phosphate	N/A	N/A	Barium	0.08	0.00			
Anion/Cation Ratio	1.00	Borate	N/A	N/A	Iron	2.50	0.09			
		Silicate	N/A	N/A	Potassium	512	13.1			
Carbon Dioxide					Aluminum	N/A	N/A			
Óxygen					Chromium	N/A	N/A			
					Copper	N/A	N/A			
		pH at time of sam	pling	7.50	Lead	N/A	N/A			
		pH at time of anal	ysis	6.62	Manganese	39.0	1 42			
		pH used in Calcu	lations	7.50	Nickel	N/A	N/A			

Cond	litions	Vá	Values Calculated at the Given Conditions - Amounts of Scale in Ib/1000bbl										
Temp. Gauge Press.				Gypsum CaSO4 2H2O		Anhydrite CaSO₄		Celestite SrSO		Barite BaSO		CO ₂ Press.	
•F	psi	Index	Amount	Index	Amount	Index	Amount	Index	Amount	Index	Amount	psi	
80	0.	1.24	21.0	-0.00		0.03	69.0	-0.17		0.08	0.01	0.06	
100	0.	1.15	23.0	-0.09		0.01	26.5	-0.20		-0.13	0.01	0.11	
120	0.	1.08	25.0	-0.16		0.02	41.2	-0.22	i i	-0.31		0.18	
140	0.	1.02	27.3	-0.22		0:05	104	-0.23		-0.48		0.27	

Note 1. When assessing the severity of the scale problem, both the saturation index (\$1) and amount of scale must be considered.

Note 2: Precipitation of each scale is considered separately. Total scale will be less than the sum of the amounts of the five scales

Note 3: The reported CO₂ pressure is actually the calculated CO₂ fugacity. It is usually nearly the same as the CO₂ partial pressure.



Water Analysis Report by Baker Petrolite

McQUADRANGLE L.C.

S.R.L.G.U. WATERFLOOD

INJECTION TANK

Account Manager RANDY ALLISON

> > Ø

Summary	/	Analysis of Sample 157603 @ 75°F								
Sampling Date	8/25/00	Anions	mg/l	meq/l	Cations	mg/l	meg/l			
Analysis Date	8/30/00	Chloride	32000	903	Sodium	19452	846			
Analyst	JOANNA RAGAN	Bicarbonate	622	10.2	Magnesium	857	70.5			
		Carbonate	0.00	0.00	Calcium	1313	65.5			
TD\$ (mg/l or g/m³)	58078.3	Sulfate	3606	75.1	Strontlum	37.0	0.84			
Density (g/cm³ or tonne/m³)	1.040	Phosphate	N/A	N/A	Barium	1.00	0.01			
Anion/Cation Ratio	1.00	Borate	N/A	N/A	Iron	1.00	0.04			
		Silicate	N/A	N/A	Potassium	189	4.83			
Carbon Dioxide	100 PPM				Aluminum	N/A	N/A			
Oxygen	i	Hydrogen Sulfide		90 PPM	Chromium	N/A	N/A			
					Copper	N/A	N/A			
		pH at time of sampling		7.00	Lead	N/A	N/A			
		pH at time of analysis		·	Manganese	N/A	N/A			
		pH used in Calculation	s	7.00	Nickel	N/A	N/A			

Çond	litions	Values Calculated at the Given Conditions - Amounts of Scale in Ib/1000bbl									Ы	
Temp. Gauge Press. 'F psi	Gauge Calcite		Gyp.	Gypsum CaSO ₄ 2H ₂ O		Anhydrite CaSO∡		Celestite SrSO₄		Barite BaSO		
	psi	Index	Amount	Index	Amount	Index	Amount	Index	Amount	Index	Amount	psi
80	0.	0.58	41.6	-0.13		-0.17		0.09	5.09	1.65	0.56	0.54
100	0.	0.68	51.0	-0.16		-0.14		0.09	4.74	1.48	0.55	0.72
120	0.	0.78	61.1	-0.18		+0.08		0.09	4.92	1.34	0.55	0 92
140	0.	88.0	71.6	-0.20		-0.00		0.10	5.54	1.21	0.54	1 17

Note 1. When assessing the seventy of the scale problem, both the saturation index (SI) and amount of scale must be considered.

Note 2. Precipitation of each scale is considered separately. Total scale will be less than the sum of the amounts of the five scales.

Note 3. The reported CO₂ pressure is actually the calculated CO₂ fugacity. It is usually nearly the same as the CO₂ partial pressure

PRODUCT WARRANTY, DISCLAIMER AND LIMITATION OF PABILITY ARE FOUND ON THE BACK OF THIS SPEET

