	Draw	er DD	rom approve	.d. 6	
Drawer DD Form 3160-5 November 1983) Formerly 9-331) DEPARTMENT OF THE INTERIOR verse side) BUREAU OF LAND MANAGEMENT					
			6. IF INDIAN, ALLOT	- ,	
	' NOTICES AND RE		,		
1,		NEXELY U	7. UNIT AGRESMENT	NAME	
OIL GAS OTHER		IIIN 05 1985			
2. NAME OF OPERATOR		0011 00 1303	1 1	8. FARM OR LEASE NAME	
Marbob Energy C	orporation	Ö. C. D.	8	M. Dodd "B"	
P.O. Drawer 217	. Artesia. N. M. Al	ARTESIA, OFFICE			
4. LOCATION OF WELL (Report		ce with any State requirements.	10. FIRLD AND POOL,	OR WILDCAT	
See also space 17 below.) At surface 660 FNL 660 FEL			1	on SR Q G SA	
			11. 200., 2., 2., M., O	11. SRC., T., E., M., OR BLE. AND SURVEY OR ARRA	
14. PERMIT NO. 15. SIEVATIONS (Show whether		w whether DF. ET. CR. etc.)		Sec. 14-T17S-R29E	
		88' DF	Eddy	N.M.	
16.		· · · · · · · · · · · · · · · · · · ·		N.M.	
		Indicate Nature of Notice, Report	, or Other Data		
NOTICE	OF INTENTION TO:		UBENÇÜBNY RAPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SEUT-OFF	REPAIRING	WELL	
PRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING	CARING	
REPAIR WELL	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZIN	en well	BHT*	
(Other)	CHANGE PLANS	(Nors: Report	results of multiple completion ecompletion Report and Log f	n on Wall	
2552' to 3785' Halliburton Lit .3% CFR-2 per s to 600#-held of 2980, 3006-17-2	. Ran 4½" 11.60# J te w/15 salt, ¼# fl sack; plug down @ 2 kay. Perforated as 22-30-34-45-60-74-8	well 2/2/85, drilled 64 -55 new casing to TD, ce ocele per sack; 410 sax :40 p.m. 2/14/85. WOC 7 follows: 2834-45-54-72 3, 3108-20-74-82-88, 324 9, 3700-12-19-26-40-45-4	mented w/225 sax Class C w/6# salt 2 hrs., tested ca -78-86, 2911-26-5 7-70-79-93, 3311-	, sinq	
APPROVED BY	Tureda TI tate office use) ED FOR RECORD	TLE Production Clerk	DATE	20/85	
CONDITIONS OF APPROVA	Ale Co				

JUN 4 1985

*See Instructions on Reverse Side

. . . .