



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **OSM-73(1), Tr. #**
Lease No. **Block 1**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Frac & Acid	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loce Hills, New Mexico **May 22** **57**
19

Well No. **7** is located **1980** ft. from **[N]** line and **1980** ft. from **[E]** line of sec. **23**
Sec. 23 **17-3** **2-1** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Indefinite **344** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3600** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

RECORD OF ACID & FRAC:

- 5-5 Washed with 2 bbls. acid. Bailed 4 gallons oil per hour (rate 2.2/ HCFD)
- 5-6 Ran 254' of 5 1/2" OD 17# JS casing with 98' of 3 1/2" OD NBS tubing & Quiberson LV 5 1/2" OD x 3 1/2" OD NBS packer on bottom. Total length 2549'.
- 5-7 Loaded hole with 12 bbls. 205 HCl and 78 bbls. crude. Loaded annulus with 28 bbls. crude. Broke down with 30 ED followed by 694 ED containing 30,000# 40-60 and 30,000# 20-40 Ottawa sand. Flushed with 108 ED. Total inj. time 37 min. Avg. inj. rate 23.4 BPM. Maximum inj. pressure 1950 psig; minimum 1350; shut down 1200. Total load oil to recover 938 bbls. Used 2 Allisons and 1 blender. Job by Duvall, Inc.
- 5-8 After shut in 19 hrs. opened with 240 psig.

(Continued on Page #2)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **GENERAL AMERICAN OIL COMPANY OF TEXAS**
Address **P. O. BOX 436**
LOCE HILLS, NEW MEXICO
By **[Signature]**
Title **Field Superintendent.**

May 22, 1957

RESULTS OF ACID & FRAC:

- 5-9 Flowed 421 BO in 24 hrs. thru $3/4"$ tubing choke.
- 5-10 Flowed 410 BO in 24 hrs. thru $3/4"$ tubing choke.
- 5-11 Pulled 5 $1/2"$ free string & ran 2" EUE tubing to 3273' with
Giberson packer at 2493'.
- 5-12 Flowed 581 BO in 24 hrs. thru $3/4"$ tubing choke.
NET oil 414 bbls.

SUBSEQUENT TESTS:

- 5-15 Flowed 202 BO in 24 hrs. thru $3/4"$ tubing choke.

1. The first part of the document is a list of the names of the members of the committee.

2. The second part of the document is a list of the names of the members of the committee.

3. The third part of the document is a list of the names of the members of the committee.
4. The fourth part of the document is a list of the names of the members of the committee.
5. The fifth part of the document is a list of the names of the members of the committee.
6. The sixth part of the document is a list of the names of the members of the committee.
7. The seventh part of the document is a list of the names of the members of the committee.
8. The eighth part of the document is a list of the names of the members of the committee.
9. The ninth part of the document is a list of the names of the members of the committee.
10. The tenth part of the document is a list of the names of the members of the committee.

11. The eleventh part of the document is a list of the names of the members of the committee.

12. The twelfth part of the document is a list of the names of the members of the committee.