



(SUBMIT IN TRIPLICATE)

Land Office Las Cruces
Lease No. 028793(a)
Unit Durch A

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent Report of Sandoil XX

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Leoc Hills, N. M. Nov. 15, 1955, 19

Well No. 234 is located 2565 ft. from N line and 955 ft. from W line of sec. 19
30-2 N.M.P.M.
Grayburg-Jackson Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3627 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)
RECORD OF PRODUCTION (FRI & T) TREATMENT: Pumped 6 BBL. Total Prod. 33,725 BU.

RECORD OF RECOMPLETION (1955):

- 10-24 Ran 87 fts. 4-1/2" OD EUS to 2484' w/c-1 H-W packer & H-1 hydr. anchor on bottom. Pumped 20 BU down annulus before setting packer & loaded annulus above packer w/51 BU.
- 10-25 Fractured as follows: Loaded w/123 BU. Broke formation down w/51 BU at 1400 psig. 222 bbls. of 24 deg. API refined oil & 151 Bbls. crude containing 22,500 lbs. sand. Flushed w/81 BU. Max. inj. press. 2100 psig; at end of flush 1900 psig, dropping to 1600 psig upon stopping pump. Total inj. time 25 min. Avg. inj. rate 18.3 BPM. 2 FIV & 2 AP pumps by Dowell. Load oil 679 BU. Flowed 40 bbls. Palled 4-1/2" EUS. Ran bailer, sand at 3123'.

RESULTS OF TREATMENT:

10-26 Ran 2" EUS tubing. Ficked off w/sand.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.
Continued on page 2.

Company General American Oil Co. of Texas
Box 416
Address Leoc Hills, N. M.

By R. J. Heard
Title Field Supt.

General American Oil Co. of Texas

Page #2

Subsequent Report of Sandoil, Burch A-23.

November 15, 1955

RESULTS OF TREATMENT (Cont'd):

10-27 Flowed 132 bbls.
10-28 Flowed 235 bbls.
10-29 Flowed 109 bbls.
10-30 Flowed 40 bbls.
10-31 Flowed 50 bbls.
11- 1 Flowed 48 bbls.
11- 2 Flowed 47 bbls. NET 22 BO.

SUBSEQUENT TESTS:

11-13 Flowed 27 BO.
11-14 Flowed 27 BO.

... ..
... ..
... ..

... ..

... ..
... ..
... ..
... ..
... ..
... ..
... ..

... ..

... ..
... ..