## N.M.O.C.D. COPY

File V

## **UNITED STATES**

7	Form Approved. Budget Bureau No. 42-R142				
LEASE	200801 Baleau No. 42-R1424				
LC-029395	(b)				

DEPARTMENT OF THE INTERIOR		LC-029	9395 (ъ)			
GEOLOGICAL SURVEY	6.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	<del></del>		REEMENT N	···	NECEN	
1. oil gas other WIW		Turner		ИE.	SEP 22	1980
2. NAME OF OPERATOR ARCO Oil & Gas Company	9.	. WELL NO #78	J.		0. C. D	)
Divison of Atlantic Richfield Company	10.		R WILDCAT I	NAME	ARTESIA, OFF	ĪŒ
3. ADDRESS OF OPERATOR		Graybı	irg Jacks	son		_
P.O. Box 1710, Hobbs, N.M. 8824-	11.	. SEC., T., AREA	R., M., OR	BLK. A	ND SURVEY OF	₹
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)		•	20-T17S-I	231E		
AT SURFACE: 2080' FSL & 1980' FEL (Unit Letter			OR PARISH		STATE	-
AT TOP PROD. INTERVAL:  AT TOTAL PERTU.		Eddy		NM		
AT TOTAL DEPTH: As Above	14.	API NO.				-
<ol> <li>CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA</li> </ol>						
REPORT, OR OTHER DATA	15.			DF, I	KDB, AND WD	)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		3688'	GR			
TEST WATER SHUT-OFF						•
FRACTURE TREAT	<b>.</b> / F					
REPAIR WELL RECLI	V	OTE: Repor	rt results of m	ultinia	ompletion or zone	
PULL OR ALTER CASING 🔲		chang	ge on Form 9-	330.)	ompletion or zone	9
MULTIPLE COMPLETE	198	80				
ADANDONIS						
(other) II. S. GEULUGIC	JAL :	PUKAFĀ	**			
ARTESIA. NE	W MI	EXIUU			• • •	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	rectio	onally drill	led give sub	give p surfac	pertinent dates e locations and	i
<ol> <li>On 10-1-79 POH w/ pkr &amp; 2 3/8" od plastic tbg. ok.</li> </ol>	lin	ned inj	ection t	bg.	Pres test	:eđ
2. RIH w/ Model AD Tension Pkr on 2 3/8 od El corrosion inhibited water in 2 3/8" X 4½" tension. Connected up wellhead and resume	ann	nulus,	set pkr	@ 29	37' w/ 14,	,000#
3046-3151' & 3421-3468' on 10-2-79.						
			8 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
			,			
Subsurface Safety Valve: Manu. and Type		W-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	Set	@	Ft	
18. I hereby certify that the foregoing is true and correct				_		
SIGNED D. L. Shackelford TITLE Engry. Tech. S	Spec	POATE	9-10-80			_
ACCEPTED FOR RECORDING space for Federal or State office	e use	.)	<del></del>		*****	
APPROVED BY APPROVAL IF ANY:		DATE _		<u> </u>		
SEP 1 5 1980						
U.S. GEOLOGICAL SURVEY						
ROSWILL NEW MEXICO . See Instructions on Reverse Si	de					