5-USC 1-R. Dec. 1973 UNITED S DEPARTMENT OF GEOLOGICAL	STARRAK-TULSA 1-	5. LEASE LC-029420 (B) 6. IF INDIAN, ALLOTTEE OF	UTEOU No. 42-R1424 R TRIBE NAME	
 SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR Getty Oil Company 3. ADDRESS OF OPERATOR P. O. BOX 730, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit Letter A 660' FNL & 760' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 15. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 		7. UNIT AGREEMENT NAM	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME	
		Skelly Unit 9. WELL NO. 129 10. FIELD OR WILDCAT NAME		
		Fren 7-Rivers 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-17S-31E		
		12. COUNTY OR PARISH 13. STATE Eddy New Mexico 14. API NO. 14. API NO.		
		15. ELEVATIONS (SHOW DF, KDB, AND WD) 3826' Gr.		
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Casing Connections	OFF			
 DESCRIBE PROPOSED OR COM including estimated date of start measured and true vertical depth 	PLETED OPERATIONS (Clearly sta ing any proposed work. If well is s for all markers and zones pertin	directionally drilled give subsu	ve pertinent dates, rface locations and	
Riser on <u>85/8" OD</u>	and <u>5 1/2" OD</u> casing b	rought to surface.	RECEIVED	
Inspected by B. W. We Inspected by Mike Wil Inspected by James Br Inspected by Bird Jon	liams (NHOCC) on asfield (USGS) on	APR 27 1979	MAY 7 1979 G. C. C.	
Subsurface Safety Valve: Manu. and T 18. Thereby certify that the foregoing SIGNED		Set @ APR 3 (
APPROVED BY THE CONDITIONS OF APPROVAL, IF ANY	This space for Federal or State ACTING DISTRIC	office use) TENGINEERE MA	<u>4</u> - 1979	
	*See Instructions on Revers		 Sole (Second Second Seco	