

(SUBMIT IN TRIPLICATE)

Land Office

Lease No. 20443

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	1	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1957

Well No. 2-1 is located 42 ft. from N line and 12 ft. from E line of sec. 1

14 Sec. and Sec. No. (Twp.) (Range) (Meridian)

~~_____~~ Indesignated _____
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 334 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. The above information is being furnished to you for your information only. It is not to be used for any other purpose.

I will let you know if I can, using sufficient care to be sure.

4 5 1/2" oil string will be cemented thru and set with 150 sacks.

is the only one that can be used by the public health survey.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John L. Case

Address 7000 130th Ave. N.E.

By _____

Title 44-38861