

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN T. DATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-067858

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CAMPALCO "C" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

EMPIRE Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

11-18-27 NM PM

12. COUNTY OR PARISH 13. STATE

EDDY

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐	NAME CHANGED: FROM: PAN AMERICAN PETR. CORP. TO: AMOCO PRODUCTION CO. EFFECTIVE: 2-1-71
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	
3. ADDRESS OF OPERATOR BOX 68, HOESBS, N. M. 88240	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL x 1980' FEL Sec. 11 (Unit B, NW 1/4 NE 1/4)	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3611' R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance with proposed work on
Form 9-331 submitted 10-15-68, Acidized
perforations 6138-58' w/ 1000 gal 95% HSTNE
Evaluated and restored to production.

Prior. Well flowed by heads - 128 BO x 9BW 24 hr. GOR 914.
After - Flow 18 1/4" CN. 142 BO x 1BW 15 hr. TPF 290. GOR 549.

TD- 6260'
PRD- 6212'
PERFS - 6138-58'
5 1/2" CSA 6260'

OC- 10-15-68

COMP- 10-19-68

RECEIVED

OCT 24 1968

OCT 2 1968

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE OCT 22 1968

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

0+4- USGS-ART
1- NSW
1- SUSP
1- RRV
1- ATLANTIC

APPROVED
OCT 22 1968
R. L. BELMONT
ACTING DIRECTOR

*See Instructions on Reverse Side