



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LAND OFFICE _____

LEASE NO. NM-04175-B

UNIT G

Co. Lease No. 231616

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

CHALK BLUFF DRAW "C"

July 14, _____, 1959

WELL NO. 1 IS LOCATED 1980 FT. FROM {N} LINE AND 1980 FT. FROM {E} LINE OF SEC. 17
SW/4 of NE/4 of Sec. 17 T-18-S R-27-E NMPM
(1/4 SEC. AND SEC. NO.) (TWP.) (RANGE) (MERIDIAN)
Wildcat Eddy County New Mexico
(FIELD) (COUNTY OR SUBDIVISION) (STATE OR TERRITORY)

THE ELEVATION OF THE DERRICK FLOOR ABOVE SEA LEVEL IS Later FT.

DETAILS OF WORK

(STATE NAMES OF AND EXPECTED DEPTHS TO OBJECTIVE SANDS; SHOW SIZES, WEIGHTS, AND LENGTHS OF PROPOSED CASINGS; INDICATE MUDDING JOBS, CEMENTING POINTS, AND ALL OTHER IMPORTANT PROPOSED WORK.)

Ran 9607.30° 5-3/2" casing, 230 jts. Set at 9621.05°. Cemented w/ 570 sacks 12% gel cement w/ 1/4# BJ R-5 per sack. Plug on bottom at 12:30 PM, 7-12-59. Ran temperature survey. Found top of cement at 6300°. Tested casing with 1500# for 30 minutes. No drop in pressure.

I UNDERSTAND THAT THIS PLAN OF WORK MUST RECEIVE APPROVAL IN WRITING BY THE GEOLOGICAL SURVEY BEFORE OPERATIONS MAY BE COMMENCED.

COMPANY Humble Oil & Refining Company

ADDRESS Box 2347 - Hobbs, New Mexico

ORIGINAL
SIGNED: R. R. ALWORTH

By _____

TITLE Agent