



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **028772 (b)**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 6, 1958

Dunn B
Well No. **# 8** is located **660** ft. from **W** line and **1900** ft. from **E** line of sec. **12**
SE/4 Sec. 12 (1/4 Sec. and Sec. No.) **16 S** (Twp.) **28 E** (Range) **RMFM** (Meridian)
Artesia (Field) **Eddy** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **3641** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We deepened above well from original total depth 2717' to 2901'. Ran 4 1/2" O.D. 9.5# casing to 2901' with back off nipple at 2232' and cemented with 100 sax. After waiting on cement 48 hrs., pressured up on casing and cement job tested O.K. Ran Gamma-Ray Neutron survey to total depth.

Now preparing to perforate and free.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Western - Yates**

Address **P. O. Box 427**

Artesia, New Mexico

By **W B Macey**

Title **Chairman of Operating Committee**