1 10. 0. Binden 102211 = -	FILE Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	LC-029420 (b)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
1. oil gas well W well other	Skelly Unit
2. NAME OF OPERATOR	92
Getty Oil Company	Grayburg Jackson (SR G J.SH)
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
P. O. Box 730, Hobbs, NA 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: Unit Letter E 1980' FNL & 660' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Eddy New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3768' DF
REPAIR WELL L L   PULL OR ALTER CASING I   MULTIPLE COMPLETE I   CHANGE ZONES I   ABANDON* I   (other) Casing Connections	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin	
Riser on <u>8 5/8" OD</u> and <u>5 1/2" OD</u> casing b	rought to surface. RECEIVE
	JUL 1 0 1979
Inspected by B. W. Weaver (NMOCC) on	  
Inspected by Mike Williams (NMOCC) on	ARTESIA, OFFIC
Inspected by James Brasfield (USGS) on	MAY 2 1979
Inspected by Bird Jones (USGS) on	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	HAN 0 1070
18. I hereby certify that the foregoing is true and correct SIGNED	ptDATENAT & 13/3
D. R. Crockett	
(Orig. Sgd.) JOE G. LARK TITLE TITLE DISTRICT	

•See Instructions on Reverse Side

.