

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY  
 FEB 01 1984  
 O.C.D.  
 ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-3852
7. Unit Agreement Name
8. Farm or Lease Name Gilmore State
9. Well No. #2
10. Field and Pool, or Wildcat Artesia Q GR SA
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Collier & Collier ✓
3. Address of Operator P.O. Box 798, Artesia, New Mexico 88210
4. Location of Well UNIT LETTER N 405 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 17 TOWNSHIP 18S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3607'

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Squeeze job <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-17-84 Squeezed Loco Hills  
Approx. 15 sxs Class "C" 2% CaCl  
Pressured to 4,000# - held  
Squeezed Penrose  
With 75 sxs Class "C" 2% CaCl
- 1-19-84 Drilled cement
- 1-20-84 Drilled cement  
Pressured tested Penrose - would not hold  
Drilled cement & bridge plug
- 1/23/84 Ran tubing ato 2250'  
Hung on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Sadie Lee* TITLE Production Clerk DATE Jan. 31, 1984

APPROVED BY *Mike Williams* TITLE OIL AND GAS INSPECTOR DATE FEB 01 1984

CONDITIONS OF APPROVAL, IF ANY: