

C/SF
J.V.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NOV 14 1980

5. LEASE
LC-029392-b

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Greenwood Pregrayburg Unit Fed.D Com.

8. FARM OR LEASE NAME
Greenwood Pregrayburg Unit Fed. D Com.

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Und. Shugart Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
26-18-31

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3653.4 GL

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Amoco Production Company

3. ADDRESS OF OPERATOR
P. O. Box 68 Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 1980' FWL, Sec. 26
AT TOP PROD. INTERVAL: (Unit C, NE/4, SW/4)
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

RECEIVED

NOV 6 1980

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS, including estimated date of starting any proposed work. If well is directly drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in service unit 10-21-80. Perforated 11574'-11586' and 11623'-11630' with 2 JSPF. Acidized with 3650 gal. MS acid with additives. Swabbed three days; recovered no gas and no oil. Set a cast iron bridge plug at 11548'. Perforated 11512'-11516' with 2 JSPF. Currently flow testing.

0+4-USGS, A 1-Hou 1-Susp 1-W. Stafford, Hou 1-Conoco

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Benton Green TITLE Ast. Admin. Analyst DATE 11-4-80

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD
NOV 10 1980
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO