COMPANY	NY SOUTHLAND ROYALTY	Well P	PARKWAY COMM 17#1		<b>Date</b> 8-29-84	
Test #	Items Tested	Pressure Pt.	Pressure	Minutes Held	Results	
1	Pipe rams, Kill-líne & chokelíne valves	Down drill pipe	0		Leak thru pipe rams, operate	
2	3	=	0		. Yellowiacket te	
ω	=	=	500#		KO .	
4	=	-	0		Leak by Yellowjacket plug, re	reset
5		=	1000#		thru pipe rams and ins ill-line at stack	de flange
	85' 8 5/8 casing with Yellowjacket packer, Hydril inside chokeline & kill-	Down drill pipe	500#		ak, stack not	
	Line					
7	=	=	1500#		Leak lost & repressure 3 times Hydril, operate	es. Thru
8	Closed pipe rams	-	1500#			k thru pij
6	=		1500#		lost & repressure 2 pipe rams	times. leak
10	=	=	1500#		Leak, same	
11	=	=	1500#		same and inside flange t stack	on
12	Hydril 85' casing inside chokeline & kill-line with Yellowjacket packer	=	1500#		с <b>,</b> 1 1 Ну	leak
 	=	=	1500#		Leak by Yellowjacket packer &	& Hydril
14	Blind rams, inside kill-line & manifold	Gauge connection	3000#	6 min	Loss & repressure, No visible	e leak
15	Kill-line check outside manifold		3000#	10 min	No visible leaks	
16	Pipe rams, inside chokeline & kill-line	Down drill pipe	2000#	<	Leak thru pipe rams, rig co	could not kee
17	1	=	3000#	5 min	leak	
18	85' casing Hydril inside chokeline & kill-line with Yellowjacket packer	Down drill pipe	1500#		visible	